6/00

1.

63

MISCELLANEOUS CHART CORRECTIONS

Chart: SAN SC 4 (New Edition, N to M 53/00 refers).

Bottom right hand corner of chart. Insert: New Edition 31/03/2000 All N to M Corrections Bottom left hand corner of chart. Delete:

SOUTH AFRICA, South Coast - Agulhas Bank - EM Control Buoy - Restricted Area established.

with radius 500m centred on EM Control Buoy Insert: in approximate position 34°54′.8 S., 021°47.6 E.

SAN Charts: (52/00)122

Source: SOEKOR (SAN 122)

*65

SOUTH AFRICA, South Coast - Agulhas Bank - ORIBI and ORYX OILFIELDS -Submarine Pipelines Laid - Entry Prohibited Area established - Fishing and Anchoring Prohibited Area established.

Accompanying Chart Block Corrections 1. Insert:

> 35°14' S., 021°30' E. in approximate position;

2. Insert: Accompanying Note Block Correction Oil and Gas Fields/Olie en Gasvelde

in approximate position; 34°03' S., 021°17' E.

(1) (1, 2) SAN Charts: (64/00)

81 (INT 7510) (52/00)

Source: SOEKOR (SAN 122, 81)

2.

*66

SOUTH AFRICA, South-West Coast - Agulhas Bank - Wells

in positions 34°52'.76 S., 022°00'.07 E. Insert: Wells: : a. 34°55'.13 S., 021°38'.13 E.

SAN Chart: 122 (65/00)

Source: Hydrographer (SAN 122)

*67

SOUTH AFRICA, South Coast - Cape Recife - Light Characteristic

1. Amend: Characteristic of light to read

F&LFI.30s28m21/29M a. & F&FI.R.30s28m10/15M

F&LFI.15/29M

in approximate position 34°01'.7 S., 025°42'.1 E.

2. Note: The light is temporarily F&LFI(3)WR.117s whilst repairs are being carried out to 2 lenses.

SAN Chart: (36/00) 1024 (a) 125 (a) (36/00) 126 (a) (36/00)57 (b) (60/00)58 (b) (36/00) 83 (INT 7530) (a) (36/00)SC 9 (a) (36/00)

Source: Hydrographer (SAN 57, 58, 83, 125, 126, 1024, SC 9)

6/00

3.

*68(T)

SOUTH AFRICA, South Coast - Port Elizabeth - Port Control.

Insert : Legend. Caution : No Radar assistance or monitoring available.

> in approximate position 33°57'.3 S., 025°38'.3 E.

The Port Control Building is being refurbished to facilitate installation of a new VTS system. Radar assistance and monitoring will not be possible until September 2000.

SAN Chart: 1024 (67/00)

> 1025 (Port Elizabeth Plan) (33/00)

Source: Hydrographer (SAN 1024, 1025)

*69

SOUTH AFRICA, East Coast - Durnford Point - Racon.

at Durnford Point Lighthouse Racon(O) Insert:

28°55'.00 S., 031°55'.30 E. in position

SAN Chart: (36/00)61

(36/00)

Source: Hydrographer (SAN 60, 61)

IA

6/00

4.

LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION (INAHINA) in 2000.

1998 Series

2MOZ(T)	Port of Beira -	Lit Waverider buoy laid.
3MOZ(P)	Port of Beira -	White Spar buoy laid.
4MOZ(T)	Port of Maputo -	No. 4 Buov temp, unlit.

1999 Series

02MOZ(P)/99	Port of Maputo -	No. 2S Buoy characteristic changed.
03MOZ(T)/99	Port of Mocimboa da Praia -	No. 9, 13, 14 Buoys withdrawn.

08MOZ(T)/99 Port of Beira - New Buoyage. 12MOZ(P)/99 Port of Quelimane - Depths.

13MOZ(T)/99 Port of Inhambane - Ponta Zavora (D6528) temp. unlit.

21MOZ(T)/99 Port of Maputo - Racon on Buoy No. 1N. temp. withdrawn.

2000 Series

02MOZ(T)/00 Port of Pemba (Amelia) - Romero Light (D6630) temp. unlit.

Nil in June.

6/00

5.

70

CORRECTION TO CATALOGUE AND INDEXES OF SAN CHARTS AND OTHER PUBLICATIONS - SAN HO-3 (NEW EDITION 1999).

1. pg 10, 11, 32. Chart SAN 103.

Delete: All references. Chart permanently withdrawn.

71

CORRECTIONS TO SOUTH AFRICAN SAILING DIRECTIONS VOL II. SAN HO-22 (NEW EDITION 1995).

1. pg viii, 1-5, 1-16.

Delete: All references to Chart SAN 103. Chart permanently withdrawn.

72

CORRECTIONS TO LIST OF LIGHTS AND RADIO SIGNALS - SAN HO 1 (NEW EDITION 2000)

1. pg 20 Cape Recife Z6100 (D6390)

Substitute: FF1.RW.30s (col 4)

Insert: After line 3 in col 8

FFI(3)RW.117s (fl 2.8, ec 27.2, fl 2.8, ec 27.2, fl 2.8, ec 54.2)

Temporary 2000 (col 8)

2. pg 36 RACON LISTING SOUTH AFRICA

Insert: 7393 (col 1)

EM Control Buoy(Z6031)

(3 & 10 cm) **X** (col 2) 360° (col 3) 12 n miles (col 4) 34°54'.8 S 21°47'.6 E (col 5)

(Note; Fitted with a 9.5kHz Submarine Warning Pinger Beacon)