

To accompany Notice to Mariners No 96 of 2001.

**SAN 1003 Port Nolloth Panel**

**SHOALING**

Shoaling occurs periodically in the approach channel and alongside the jetty. The NW corner of the jetty is unusable by any craft other than shallow draft vessels. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 96 of 2001.

**SAN 1003 Port Nolloth Panel**

**SHOALING**

Shoaling occurs periodically in the approach channel and alongside the jetty. The NW corner of the jetty is unusable by any craft other than shallow draft vessels. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 97 of 2001.

**SAN 1003 Lambert's Bay Panel**

**SHOALING**

Shoaling occurs periodically in the approach channel and alongside the jetties. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 97 of 2001.

**SAN 1003 Lambert's Bay Panel**

**SHOALING**

Shoaling occurs periodically in the approach channel and alongside the jetties. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 98 of 2001.

**SAN SC 3**

**SHOALING**

Shoaling occurs periodically in the approach channel to Laaiplek and alongside the jetties as well as in the river towards Carinus Bridge, also in the approach channel to Lambert's Bay and alongside the jetties. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 98 of 2001.

**SAN SC 3**

**SHOALING**

Shoaling occurs periodically in the approach channel to Laaiplek and alongside the jetties as well as in the river towards Carinus Bridge, also in the approach channel to Lambert's Bay and alongside the jetties. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 99 of 2001.

**SAN 1009**

**SHOALING**

Shoaling occurs periodically in the approach channel to Laaiplek and alongside the jetties as well as in the river towards Carinus Bridge. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.

To accompany Notice to Mariners No 99 of 2001.

**SAN 1009**

**SHOALING**

Shoaling occurs periodically in the approach channel to Laaiplek and alongside the jetties as well as in the river towards Carinus Bridge. Vessels to observe extreme caution and to confirm situation with Harbour Master before entering harbour.